

German Work Box Optimization Chart

Attached is an optimization plan for cutting the necessary two sheets of 3/4" and one sheet of 1/2" plywood. The red dashed lines indicate the first cuts in separating the plywood. This isn't the only way to cut the plywood, but does make it manageable and guarantees all the pieces will be possible.

